12.3____**F30 INDASH**___

____**Linux**___

0040000000000012000000








Instrument Installation Steps









- 1. USB interface (for upgrading instruments)
- 2. Original vehicle instrument power line interface
- 3. Original vehicle instrument fiber optic interface (note: 3 series does not have this interface)

Accessory

- Loading tool (note: 3 Series does not have this accessory)
- 2. USB (for upgrading instruments)

