

12.3 吋 GPS 雙螢幕 Android 雙螢幕 Land Rover Sport 2014 2015 2016 2017 PX6HD 雙 螢幕 雙 螢幕 Carplay Auto STEREO

雙 螢幕



















□□

□	□
□□	□□ □ 1din
□□ □□	ips
□□ □□	12.3 ""
□□	□□□□, □□, □□ □□□, □□ □ DSP
□□	USB, SIM □□, □□ □□□□
□□□□□	□□□ □□, FM □□□
□□	12V
□□□ □□	64GB
□□	1 □
□□	CE, FCC, ROHS
□□□	□□
Wi -Fi □□□	□□ Wi-Fi □□□
□□□	3G/4G/WiFi□ □□□□□

GPS 雙頻雙天線 支援 GoogleMap 網路地圖

雙頻雙天線 支援 網路地圖 網路地圖

雙頻雙天線 支援

支援 網路地圖 : Citroen C3-RX 等車

支援 Google Play 網路地圖

DSP 支援 網路地圖

支援 網路地圖 3 天, 網路地圖 : 20-25s


10 天 網路地圖 : 網路 / 網路 / 網路 / 網路 / 網路 / 網路 / 網路 / 網路

OSD 網路 / 網路 / 網路

/ 網路 / 網路 / 網路

COMPLETE FUNCTION

Not only for car gps , let's play car pad.



ORIGINAL VEHICLE CONTROL

Easy to switch songs, channels and adjust volume, provide you a safer and more enjoyable journey.



NAVIGATION

Support online and off-line navi app, such as Google map, igo map, support 3DMaps and voice guidance.



BUILT-IN DSP SYSTEM

32-band EQ , which can adjust the frequency of subwoofer , bass , mid-bass , mid-range, mid-treble , treble , super-treble.

Time Delay

Best Sound Position

We Call Emperor
Position



MIRROR LINK

Support mirror link with Android phone and iphone.



ABOUT INSTALLATION

It is plug and play for installation , without broken wire , does not affect the normal warranty of 4s shop.



NXP7850 RADIO CHIP

The NXP7850 radio chip is better than the original car , supports the RDS function , hasless noise , and has a stronger closing sensitivity.



HIGH RESOLUTION

High resolution with more pixels , clearer and more development , and the stronger the visual sense layering.



BUILT-IN CARPLAY

Carplay is a smarter , safer way to use your iphone while you drive. You can get directions , make calls , send and receive messages, and enjoy your favorite music.



CAR GAUGE CHIP

The chip can work normally at temperatures from +80 c to -30 c, with faster speeds.



MIRROR LINK

Support mirror link with Android phone and iphone.



ABOUT INSTALLATION

It is plug and play for installation , without broken wire , does not affect the normal warranty of 4s shop.

